

COLORADO CULTURAL RESOURCES INVENTORY

Greeley 8th Avenue Survey

Historical and Architectural Reconnaissance Form

OAHP Site #: **5.WL.7853**

Eligibility Evaluation (OAHP use only)

Date _____ Initials _____

____ Determined Eligible – NR

____ Determined Eligible - SR

____ Needs Data

____ Eligible District – Contributing

____ Eligible District - Noncontributing

IDENTIFICATION

1. Current Property Name: **Tainted Hearts Tattoo and Body Piercing**
Historic Property Name **H. M. Hansen Machine Shop**
2. Resource Classification: **Building**
3. Ownership: **Private**
Owner(s) contact info:

LOCATION

4. Street Address: **1008 / 1010 8th Avenue**
5. Municipality: **Greeley, Colorado**
6. County: **Weld**
7. USGS Quad (7.5'): **Greeley, Colorado** year: **1950** **Photorevised 1980**
8. Parcel Number: **096105336023**
9. Parcel Information: Lot(s): **7** Block: **78** Addition: **Greeley Original Townsite**
10. Acreage: **< 1**
11. PLSS information: Principal Meridian: **6th** Township: **5 North** Range: **65 West**
SE¹/₄ SW¹/₄ SE¹/₄ SW ¹/₄ of section 5
12. Location Coordinates: **Zone 13** **526257 mE** **4474633 mN**
Datum: NAD83

DESCRIPTION

13. Construction features (forms, materials)

Property Type: **Building**

Building Plan: **Rectangular Plan**

Dimensions in Feet: **35' N-S by 10' E-W**

Stories: **One**

Architectural Style/Type: **Early Twentieth Century Commercial**

Foundation: **Concrete**

Walls: **The upper façade, brick columns at either end of the façade, and a center column between the two storefronts, are clad with white metal panels which are applied over the original brown brick façade wall. Three brown brick courses are exposed**

at the top of the parapet on the façade. The east and north walls are clad with troweled beige color stucco over brown brick wall construction.

Windows:

The lower façade (west elevation) is divided into two storefronts, each angled inward from the corners to the middle where they are divided by a center column. Each storefront contains floor-to-ceiling fixed-pane windows set in silver metal frames. These windows are to the outside (north and south) ends of the storefronts, while the entry doors are to the inside of the storefronts. A flat metal awning, with a green cloth canopy, extends out over the sidewalk above both storefronts. The north wall contains two small single-light fixed-pane windows in brown metal frames. There are no windows on the east (rear) elevation.

Roof:

The roof is flat, with parapets on the north, west, and south.

Chimney(s):

N/A

Porch(s) / Doors:

The lower façade (west elevation) is divided into two storefronts, each angled inward from the corners to the middle where they are divided by a center column. The north storefront is addressed as 1008 8th Avenue, and is currently occupied by "Tainted Hearts Tattoo & Body Piercing." The south storefront is addressed as 1010 8th Avenue, and is currently used as storage for "Steven's Auto Parts" which occupies the adjacent building to the south. Each storefront contains a glass-in-silver-metal-frame door, flanked by floor-to-ceiling fixed-pane windows. Two white metal-paneled doors, each covered by a storm door, enter the east (rear) elevation.

14. Landscape (important features of the immediate environment)

- Garden
- Mature Plantings
- Designed Landscape
- Walls
- Parking Lot
- Driveway
- Sidewalk
- Fence
- Seating

HISTORICAL ASSOCIATIONS

15. Historic function/use: **Commerce /Trade (machine shop)**

Current function/use: **Commerce/Trade / Specialty Store (tattoo and body piercing shop)**

16. Date of Construction: **Circa 1926 (per city directories, Assessor records, and Sanborn maps)**

17. Other Significant Dates: **N/A**

18. Associated NR Areas of Significance

- Agriculture
- Architecture
- Archaeology
- Art
- Commerce
- Community Planning & Development
- Conservation
- Economics
- Education
- Engineering
- Entertainment/Rec.
- Ethnic Heritage
- Exploration/Settlement
- Health/Medicine
- Industry
- Invention
- Landscape Architecture
- Law
- Literature
- Maritime History
- Military
- Performing Arts
- Philosophy
- Politics/Gov't.
- Religion
- Science
- Social History
- Transportation
- Other

19. Associated Historic Context(s) (if known): **City of Greeley 8th Avenue Survey; Greeley Downtown Historic District**

20. Retains Integrity of: Location Setting Materials Design Workmanship Association Feeling

21. Notes:

This building is located on the east side of the 1000 block of 8th Avenue. Another commercial building at 1012 8th Avenue is adjacent to the south. A Carl's Jr. fast food burger restaurant is to the northeast.

22. Sources:

The Greeley City and Rural Route Directory. (Generally published annually by *the Greeley Tribune-Republican Publishing Company*.)

Sanborn Insurance Company maps for Greeley, Colorado dated June 1886, December 1887, January 1891, October 1895, January 1901, January 1906, October 1909, January 1918, April 1927, September 1946 (as an update of the April 1927 Sanborn maps), August 1968 (also as an update of the April 1927 Sanborn maps).

Weld County Assessor Property Information Map. <http://www.co.weld.co.us/maps/propertyinformation>

Weld County Assessor Property reports. <https://propertyreport.co.weld.co.us>

FIELD ELIGIBILITY RECOMMENDATIONS

Local Landmark Eligible? yes no needs data

Individually State Register Eligible? yes no needs data


Individually National Register Eligible? yes no needs data

Contributes to a Potential Historic District? yes no needs data property is not located within a potential district

RECORDING INFORMATION

Recorded by:	Carl McWilliams	Date: November 30, 2015
Affiliation/Organization:	Cultural Resource Historians LLC	Phone Number: (970) 493-5270
Report title:	Greeley 8th Avenue Comprehensive Historic Resource Survey	
Project Sponsor:	City of Greeley Historic Preservation Office	
Photo Log:	CD 1, Images 136, 144, 145	



SKETCH PLAN



LOCATION MAP

1008/1010 8th Avenue

AllTrails NATIONAL GEOGRAPHIC





CD 1, Image 136, View to ESE of façade (west)



CD 1, Image 144, View to SE of façade (west) and north side



CD 1, Image 145, View to SW of rear (east) and north side